

HSS

RECEIVED*By Chris at 1:16 pm, Aug 01, 2019*

Osteolysis

Most patients successfully recover from joint replacement surgery with no complications. But occasionally, “wear debris” from the breakdown of materials in the hip or knee implant can accumulate in the surrounding tissues. This causes local inflammation that destroys the bone and loosens the prosthesis, a condition called **osteolysis**.

Explore osteolysis



Research

[New Technologies to Treat Inflammation and Pain](#)[Osteolysis Research: New Discoveries](#)[Joint Replacement: Implant Bearing Surface Materials](#)

Back in the Game Patient Stories

